

Menu


HISTORY FILE MAP for year 2001

Realtime

Playback

Recalled Realtime

Recalled Playback



DSS43 dropped uplink again because of an exciter problem. 9m loss of 1024bps data from additional 2-way to 1-way to 2 way switchings. DR A05118 refers.

DSS43 dropped uplink because of an exciter problem. 6m loss of 1024bps data from additional 2-way to 1-way to 2 way switchings. DR A05117 refers.